

ITEM	PART#	QTY.	DESCRIPTION
1	1595-1	1	Winch Mount Plate
2	HDW1052	4	8mm x 25mm Flange Hex Bolt

WINCH MOUNT INSTRUCTIONS

Arctic Cat 00-07 500 Automatic, 99-01 500 Manual, 96-98 454 Bear Cat, 98-01 250/300/400 Models

Remove the (4) 8mm bolts and mesh screen on the front of the machine.

Install the winch on the mount plate (winch will hang upside down). Now install the fairlead. Both winch and fairlead will be installed with hardware provided by winch manufacturer.

Place winch mount with winch into open space you removed the screen from and attach with the (4) 8mm Hex bolt provided in the kit and tighten securely

Wire winch to manufacturers specs.

